

Phil's Cylinder Service

14833 SIDNEY-PLATTSVILLE RD
 SIDNEY OHIO 45365
 937-833-0843

WORK ORDER

WORK ORDER NO: 549001
 DATE: October 26, 2016

BENDIX MAGNETO REPAIR 2016

To:

Ship To:

MODEL	P/N	DESCRIPTION	MAKE	S/N
S6LN-21	10-51365-39	MAGNETO	BENDIX	549001

DESCRIPTION OF WORK

C/W 500 HR INSPECTION USING TCM MANUAL AS A GUIDE
 REPLACED CARBON BRUSHES
 REPLACED SEAL
 RESHIMED ROTOR
 TESTED

QUANTITY	PART DESCRIPTION
1	SNAP RINGS
1	CARBON BRUSHES
1	SEAL

The Component Identified Above was Repaired And Inspected In Accordance With Current Federal Aviation Regulations And Was Found Airworthy For Return to Service
IA A&P-400062798
Date: 10-26-2016

If you have any questions concerning this invoice, call:
 Phillip Scadden, 937-833-0843